

PUBLIC RIGHTS OF WAY DEFINITIVE MAP STATEMENTS (BCC/DMS)

| | | | |
|-------------------------|------------------------------|-------------------------------|---|
| Local Authority: | Central Bedfordshire Council | Definitive Map Details | Notes: Subsection ROWs listed in priority order |
| Parish: | Barton-Le-Clay | | |
| Type of PROW: | Footpaths | | |

| | | | | | | | | |
|---------------------------|----------------------------|--------------------|----------|-------|-----|---|-----------------------------------|---|
| a | ROW Number & Local Name | | Km Miles | | map | Grid references: | Start description: | End description: |
| | | | | | | | | |
| | FP1 | Leet Wood | 1.26 | 0.78 | TL | 082301 - 089292 | Old Road by Radworth Stables | Top and south end of Leet wood |
| | FP2a | Middle Field Path | 0.52 | 0.32 | TL | 082310 - 086310 | Old school/Bradshaws Alley | Manor Road |
| | FP2b | New Path | 0.75 | 0.45 | TL | 086310 - 090314 | Manor Road | Westhay >PB-FP58 Shillington |
| | *FP3 | Carsey Path | 0.14 | 0.07 | TL | 081313 - 080313 | South side of the Waggon PH | Jct Grange Rd & Wiffen Close |
| | FP4 | Buckworth Parth | 0.22 | 0.14 | TL | 082304 - 085304 | Old Rd opp. Washbrook Close | Church Rd opp. St Nicholas Ch |
| | FP5a | Willow End | 0.89 | 0.55 | TL | 076316 - 081323 | Willow Cottage, Faldo Rd | Old toll bridge, speed the plough |
| | FP5b | Turnpike Lane | 1.13 | 0.7 | TL | 081323 - 090326 | Old toll bridge, speed the plough | Westhay >PB-FP56 Shillington |
| | FP5c | Willow End Field | 0.29 | 0.18 | TL | 077314 - 077317 | Opp.mill entrance, Faldo Rd | Mid. FP5a |
| | FP6 | Marriots Alley | 0.7 | 0.43 | TL | 081308 - 086311 | Old Bedford Road nxt. Old Spar | Manor Road by Manor House |
| | *FP7a | Bull meadow | 0.51 | 0.32 | TL | 081310 - 077310 | Next to the Bull Inn | A6 southern barrier gap |
| | *FP7b | Brook End Green | 0.53 | 0.33 | TL | 076310 - 072309 | A6 southern barrier gap | Brook End Green Farm >BW7 |
| | *FP7c | Franklin Ave | 0.11 | 0.07 | TL | 079312 - 079311 | Mill Lane | Frranklin Ave >FP7a |
| | *FP7d | Franklin Pass. | 0.11 | 0.07 | TL | 080311 - 079311 | FP7a Frankling Avenue | FP7c Frankling Avenue |
| | *FP8 | Mill race path | 1.16 | 0.72 | TL | 076306 - 077314 | Sherrifs Wood >PP | Barton Water Mill |
| | FP9 | Longcroft Pass. | 0.09 | 0.06 | TL | 078309 - 078308 | Sharpenhoe Rd opp. FP12 | Longcroft Drive |
| | FP10 | Mill Field path | 0.52 | 0.32 | TL | 074311 - 075316 | Behind Brook End Green Fm. FP7 | Opp. Willow End Cottage FP5a |
| | FP11 | Sharpenhoe Way | 1.52 | 0.94 | TL | 076312 - 062312 | Barton Water Mill | Sharpenhoe Bury >PB-BW18 Str |
| | *FP12a | Barton Rd | 0.12 | 0.07 | TL | 072307 - 073306 | Sharpenhoe Rd opp. Brook End | Dead end, adjcent field |
| | *FP12b | Horslers paddock | 0.32 | 0.2 | TL | 074307 - 075304 | Sharpenhoe Rd opp. Brook End | Dead end, adjcent field |
| | *FP12c | Unity Hall Path | 0.32 | 0.2 | TL | 079308 - 077307 | Sharpenhoe Rd behind Unity Hall | Dead end, adjcent field |
| | FP12d | Searchlight field | 0.36 | 0.21 | TL | 076308 - 073309 | Sharpenhoe Rd FP8 Jct. | Brook End Green Farm >BW7b |
| | FP13a | Park Meadow | 0.32 | 0.2 | TL | 078310 - 076312 | Grange Road | Barton Water Mill |
| | FP13b | Faldo field path | 0.62 | 0.39 | TL | 077319 - 074325 | FP5a behind Faldo Farm | Margrett Lane >PB FP18 Pulloxhill |
| | FP14a | Airfield path | 0.99 | 0.62 | TL | 074316 - 066317 | Faldo Rd Industrial Estate | >PB FP14 Pulloxhil |
| | FP14b | Airfield path link | 0.28 | 0.17 | TL | 073317 - 072315 | Faldo Rd Industrial Estate | FP14a footbridge |
| | FP15a | Barton Springs | 0.66 | 0.41 | TL | 072318 - 069323 | Church Rd behind Rectory | Jct. FP1, FP19, BW16 Leet Wood |
| | FP15b | Higgins Wood | 1.18 | 0.73 | TL | 085303 - 089292 | Faldo Farm Entrance | >PB FP18 Pulloxhill |
| | FP16 | Stonley Wood tk | 1.08 | 0.67 | TL | 092294 - 094284 | BW16, Top of B Hills | Barton Hill Farm |
| | FP19 | Barton Hill track | 0.46 | 0.29 | TL | 092295 - 089292 | Jct. FP1, FP15, BW16 Leet Wood | BW16, Top of B Hills |
| | FP23 | Hexton Way | 0.22 | 0.14 | TL | 087311 - 089311 | Jct. FP2 behind Manor House | BW23, Hexton Way |
| | FP33 | Old Mill Lane | 0.19 | 0.12 | TL | 079312 - 077312 | Mill Lane corner | Jct. FP13, before A6 Bypass |
| | 31 | | 17.57 | 10.91 | | | | |
| Correct as of: 04/03/2018 | | | | | | | Anomalies: | Abre: |
| Total ROW | | Total km/ml | | | | FP3: gap mid section | | FP - Footpath BW - Bridleway PB – Parish Boundary PP – Permissive Path |
| 19 | | | | | | FP7: | | |
| plus 12 sub sections | | | | | | FP8: gap and deadend FP12: gap and deadend | | |

| | |
|---|-------------------------------------|
| Results: By distance percentage: RED 15.15%, AMBER 81.81%, GREEN 3.03% 9 Anomalies | COMPLETED 04/04/18 |
| | CURRENT V1.3 |

BCC Reps' SIGNATURE
Date:

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP1 n/a 20/03/18 wet Leet Wood Path |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | TL | 0824 3019 | 0838 3015 | 0838 3008 | 0853 2969 | 0892 2927 | | | |
|----------------------------|--------------------------------|-------------------------------------|--------------|--------------|--------------|--------------|--------------|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | repair | na | na | na | na | | | |
| | 2 | Waymark/other sign along path | no | missing | missing | missing | missing | | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | no | no | no | | | |
| | 4 | Steps/revetment | repair | no | no | no | no | | | |
| | 5 | Bridges (length in meters) | no | no | no | no | no | | | |
| | 6 | Styles | no | no | no | no | no | | | |
| | 7 | Gates | no | no | no | no | KG ok | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | no | | | | |
| | 2 | Tree/brough | no | no | no | no | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | | | | |
| | 4 | Illegal or misleading sign | no | no | no | no | | | | |
| | 5 | Building or structure | no | no | no | no | | | | |
| | 6 | Muddy/boggy localised | muddy | ok | ok | ok | | | | |
| | 7 | Upgrowth localised | minor | none | none | none | | | | |
| | 3: SURFACE TYPE | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | no | | | | |
| | 2 | Arable headland/field edge | headland | headland | headland | headland | | | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | | | | |
| | 4 | Surfaced (tarmac, stone etc) | Mud/grass | grass | grass | grass | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | na | na | na | | | | |
| | 2 | Headland (field edge) ploughed | no | no | no | na | | | | |
| | 3 | Path surface damaged/broken up | no | no | no | no | | | | |
| | 4 | Flooded/rutted/boggy/muddy | minor | no | no | no | | | | |
| | 5 | Upgrowth (on pathway) | minor | none | none | none | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | minor | none | none | none | | | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | no | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | no | | | | |
| | 4 | Intimidating beast/person | no | no | no | no | | | | |
| | 5 | Collapsed wall | no | no | no | no | | | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | no | | | | |
| | 7 | Quarrying or extraction | no | no | no | no | | | | |
| | 8 | Plantation for forestry | no | no | no | no | | | | |

| key | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|--------------------------|---|
| G | Good | |
| M | Missing | |
| A | Attention | |
| R | Repair/replace | FP1 is DDA compliant, however it is not when accessing the NNR. |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded yes Route GPS logged no Map attached and ammended yes

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP2A n/a 22/03/18 wet Middle Field Path |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0816 3107 | 0822 3106 | 0829 3103 | 0833 3101 | 0853 3097 | 0862 3010 | | |
|----------------------------|--------------------------------|-------------------------------------|----|--------------|--------------|--------------|--------------|--------------|--------------|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | missing | good | na | repair | good | good | | |
| | 2 | Waymark/other sign along path | | na | na | missing | na | na | na | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | no | no | good | | |
| | 4 | Steps/revetment | | repair | no | no | no | no | | | |
| | 5 | Bridges (length in meters) | | no | no | no | no | no | | | |
| | 6 | Styles | | no | no | no | no | no | | | |
| | 7 | Gates | | no | no | no | no | KG ok | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | no | no | no | | | |
| | 2 | Tree/brough | | no | no | no | no | no | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | no | no | no | | | |
| | 4 | Illegal or misleading sign | | no | no | no | no | no | | | |
| | 5 | Building or structure | | no | no | no | no | no | | | |
| | 6 | Muddy/boggy localised | | no | no | no | no | no | | | |
| | 7 | Upgrowth localised | | none | none | none | none | none | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | no | no | no | | | |
| | 2 | Arable headland/field edge | | no | no | no | no | no | | | |
| | 3 | Natural/set-aside but not above | | no | no | no | no | no | | | |
| | 4 | Surfaced (tarmac, stone etc) | | tarmac | tarmac | tarmac | tarmac | tarmac | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | na | na | na | na | na | | | |
| | 2 | Headland (field edge) ploughed | | na | na | na | na | na | | | |
| | 3 | Path surface damaged/broken up | | no | no | no | no | no | | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | no | no | no | | | |
| | 5 | Upgrowth (on pathway) | | none | none | none | none | none | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | na | minor | minor | none | minor | | | |
| | 2 | Standing water (pool/pond/lake) | | no | no | no | no | no | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | no | no | no | | | |
| | 4 | Intimidating beast/person | | no | no | no | no | no | | | |
| | 5 | Collapsed wall | | no | no | no | no | no | | | |
| | 6 | Encroachment (not by ploughing) | | no | no | no | no | no | | | |
| | 7 | Quarrying or extraction | | no | no | no | no | no | | | |
| | 8 | Plantation for forestry | | no | no | no | no | no | | | |

| key | | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--------------------------|--|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

Fingerpost at start has wayward dog fouling sign. Steps at start in poor condition. No way markers found on this route (4 junctions with NNR no posts or markers). Path is well maintained by land owner.
FP2A is not DDA compliant, due to path width at start of leg5.

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged **no** Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|------------------|--------|----------------------|--------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP2B n/a 22/03/18 wet New Path |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | TL | 0863 3101 | 0871 3109 | 0877 3114 | 0878 3114 | 0878 3125 | 0905 3146 | 0905 3147 | |
|--------------------------------|-------------------------------|-------------------------------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--|
| 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | good | na | na | na | na | na | na | |
| | 2 | Waymark/other sign along path | na | damaged | good | good | missing | good | missing | |
| | 3 | Safety/amenity barrier eg.cycle | repair | no | no | no | no | no | no | |
| | 4 | Steps/revetment | repair | no | no | no | no | no | no | |
| | 5 | Bridges (length in meters) | no | narrow 5 | no | no | no | no | narrow 2 | |
| | 6 | Styles | no | no | no | no | no | no | no | |
| | 7 | Gates | no | no | no | no | no | no | no | |
| 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | no | no | no | | |
| | 2 | Tree/brough | no | no | no | no | no | no | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | no | no | | |
| | 4 | Illegal or misleading sign | no | no | no | no | no | no | | |
| | 5 | Building or structure | no | no | no | no | no | no | | |
| | 6 | Muddy/boggy localised | no | muddy | muddy | no | no | no | | |
| | 7 | Upgrowth localised | none | minor | minor | none | none | none | | |
| 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | no | no | no | | |
| | 2 | Arable headland/field edge | no | headland | headland | headland | headland | headland | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | no | no | | |
| | 4 | Surfaced (tarmac, stone etc) | tarmac | grass | grass | grass | grass | grass | | |
| 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | na | na | na | na | na | | |
| | 2 | Headland (field edge) ploughed | na | no | no | no | no | no | | |
| | 3 | Path surface damaged/broken up | no | no | no | no | no | no | | |
| | 4 | Flooded/rutted/boggy/muddy | no | muddy | no | no | no | no | | |
| | 5 | Upgrowth (on pathway) | none | minor | minor | minor | minor | minor | | |
| 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | minor | none | minor | none | minor | minor | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | no | no | no | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | no | no | no | | |
| | 4 | Intimidating beast/person | no | no | no | no | no | no | | |
| | 5 | Collapsed wall | no | no | no | no | no | no | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | no | no | no | | |
| | 7 | Quarrying or extraction | no | no | no | no | no | no | | |
| | 8 | Plantation for forestry | no | no | no | no | no | no | | |

| | | |
|-----|---------------------------------|---|
| key | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | |
| M | Missing | |
| A | Attention | |
| R | Repair/replace | FP2B is not DDA compliant, due to bridge width at leg2 and leg7. |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP3 n/a 23/03/18 wet Carseys Path |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0813 3134 | 0810 3135 | 0807 3136 | 0800 3137 | | | | |
|----------------------------|--------------------------------|-------------------------------------|---------|--------------|--------------|--------------|--------------|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | Good | na | na | attention | | | | | |
| | 2 | Waymark/other sign along path | no | missing | missing | na | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | no | no | | | | | |
| | 4 | Steps/revetment | no | no | no | no | | | | | |
| | 5 | Bridges (length in meters) | no | no | no | no | | | | | |
| | 6 | Styles | no | no | no | no | | | | | |
| | 7 | Gates | no | no | no | no | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | | | | | | |
| | 2 | Tree/brough | no | no | no | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | | | | | | |
| | 4 | Illegal or misleading sign | no | no | no | | | | | | |
| | 5 | Building or structure | no | no | no | | | | | | |
| | 6 | Muddy/boggy localised | no | muddy | no | | | | | | |
| | 7 | Upgrowth localised | none | minor | none | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | | | | | | |
| | 2 | Arable headland/field edge | carpark | track | pavement | | | | | | |
| | 3 | Natural/set-aside but not above | no | no | no | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | tarmac | chippings | tarmac | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | no | no | no | | | | | | |
| | 2 | Headland (field edge) ploughed | no | no | no | | | | | | |
| | 3 | Path surface damaged/broken up | no | no | no | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | wet | no | | | | | | |
| | 5 | Upgrowth (on pathway) | none | minor | none | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | none | minor | none | | | | | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | | | | | | |
| | 4 | Intimidating beast/person | no | no | no | | | | | | |
| | 5 | Collapsed wall | no | no | no | | | | | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | | | | | | |
| | 7 | Quarrying or extraction | no | no | no | | | | | | |
| | 8 | Plantation for forestry | no | no | no | | | | | | |

| | | |
|------------------|---|---|
| key | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G Good | Track has minor undergrowth and is poorly surfaced for a short section. Fingerposts are ok however fingerpost at (western) end is pointing the wrong way! | |
| M Missing | Leg to Ashby Drive has been blocked by home owner, confirmation of PROW access? | |
| A Attention | FP3 is DDA compliant, however path width at leg2 is narrow. | |
| R Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP4 n/a 20/03/18 wet Buckworth Path |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0829 3039 | 0842 3038 | 0851 3040 | | | | | |
|----------------------------|--------------------------------|-------------------------------------|----|--------------|--------------|--------------|--|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | good | na | good | | | | | |
| | 2 | Waymark/other sign along path | | na | missing | na | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | | | | | |
| | 4 | Steps/revetment | | no | no | no | | | | | |
| | 5 | Bridges (length in meters) | | no | no | no | | | | | |
| | 6 | Styles | | no | no | no | | | | | |
| | 7 | Gates | | KG ok | no | no | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | | | | | | |
| | 2 | Tree/brough | | no | no | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | | | | | | |
| | 4 | Illegal or misleading sign | | no | no | | | | | | |
| | 5 | Building or structure | | no | no | | | | | | |
| | 6 | Muddy/boggy localised | | muddy | no | | | | | | |
| | 7 | Upgrowth localised | | minor | none | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | | | | | | |
| | 2 | Arable headland/field edge | | no | no | | | | | | |
| | 3 | Natural/set-aside but not above | | no | no | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | grass | tarmac | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | na | na | | | | | | |
| | 2 | Headland (field edge) ploughed | | na | na | | | | | | |
| | 3 | Path surface damaged/broken up | | no | no | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | | | | | | |
| | 5 | Upgrowth (on pathway) | | none | none | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | minor | none | | | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | no | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | | | | | | |
| | 4 | Intimidating beast/person | | no | no | | | | | | |
| | 5 | Collapsed wall | | no | no | | | | | | |
| | 6 | Encroachment (not by ploughing) | | no | no | | | | | | |
| | 7 | Quarrying or extraction | | no | no | | | | | | |
| | 8 | Plantation for forestry | | no | no | | | | | | |

| key | | Summary of work required | Added to ViewRanger data base <div>yes - no</div> BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|---|--|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |
| | | Fingerposts at start and end are good, park gate is ok. Mid path kissing gate is non RADAR with poor ground surface on Arnold Recreation Gground side. Path on Church Rd side is well maintained. | |
| | | FP4 is not DDA compliant, due to restricted access by non RADAR kissing gate. | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged **no** Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP5A n/a 18/02/18 wet Willow End |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0763 3165 | 0763 3167 | 0772 3177 | 0777 3199 | 0812 3228 | 0815 3230 | | |
|----------------------------|--------------------------------|-------------------------------------|------------|--------------|--------------|--------------|--------------|--------------|--------------|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | good | none | none | none | none | none | good | | |
| | 2 | Waymark/other sign along path | no | replace | replace | replace | replace | replace | no | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | no | no | no | no | no | | |
| | 4 | Steps/revetment | no | no | no | no | no | no | no | | |
| | 5 | Bridges (length in meters) | no | no | no | no | no | no | no | | |
| | 6 | Styles | no | no | no | no | no | no | no | | |
| | 7 | Gates | no | no | no | no | no | Sml CG | no | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | no | no | no | | | |
| | 2 | Tree/brough | no | minor | minor | no | no | no | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | no | no | | | |
| | 4 | Illegal or misleading sign | no | no | no | no | no | no | | | |
| | 5 | Building or structure | no | no | no | no | no | no | | | |
| | 6 | Muddy/boggy localised | no | no | no | no | no | no | | | |
| | 7 | Upgrowth localised | no | no | no | no | no | no | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | no | no | no | | | |
| | 2 | Arable headland/field edge | field edge | woodland | woodland | woodland | woodland | no | | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | no | no | | | |
| | 4 | Surfaced (tarmac, stone etc) | grass | mud | mud | grass | grass | gravel | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | na | na | na | na | na | | | |
| | 2 | Headland (field edge) ploughed | no | no | no | ploughed | no | no | | | |
| | 3 | Path surface damaged/broken up | no | no | no | minor | no | no | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | boggy | boggy | no | no | no | | | |
| | 5 | Upgrowth (on pathway) | mown | minor | minor | none | minor | no | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | none | minor | minor | minor | no | no | | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | no | no | no | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | no | no | no | | | |
| | 4 | Intimidating beast/person | no | no | no | no | no | no | | | |
| | 5 | Collapsed wall | no | no | no | no | no | no | | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | no | no | no | | | |
| | 7 | Quarrying or extraction | no | no | no | no | no | no | | | |
| | 8 | Plantation for forestry | no | no | no | no | no | no | | | |

| | | | |
|-----|---------------------------------|--|---|
| key | Summary of work required | | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | Fingerpost at start is good but moss covered. Waymarker posts at leg2, leg3 and leg4 are all rotten through and laying on the ground requiring replacement. Light overgroth and some low hanging tree branches in places, track wet and slippery. Crush gate at leg5 is way to narrow for able body walkers. Figer post at end good. | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | This section of FP5 is not DDA compliant, as the crush gate at leg5 is too narrow. | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP5B n/a 18/02/18 wet Turnpike Lane |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0832 1631 | 0832 4859 | 0832 6977 | 0832 8568 | 0932 0769 | 0932 0870 | | |
|----------------------------|--------------------------------|-------------------------------------|-------|--------------|--------------|--------------|--------------|--------------|--------------|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | Good | none | none | none | none | none | none | | |
| | 2 | Waymark/other sign along path | no | damaged | missing | good | good | good x2 | | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | no | no | no | no | | | |
| | 4 | Steps/revetment | no | no | no | no | no | no | | | |
| | 5 | Bridges (length in meters) | no | no | no | no | no | good 8m | | | |
| | 6 | Styles | no | no | no | no | no | no | | | |
| | 7 | Gates | no | no | no | no | no | no | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | no | no | no | | | |
| | 2 | Tree/brough | no | no | no | no | no | no | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | no | no | | | |
| | 4 | Illegal or misleading sign | no | no | no | no | no | no | | | |
| | 5 | Building or structure | no | no | no | no | no | no | | | |
| | 6 | Muddy/boggy localised | no | no | no | very | no | | | | |
| | 7 | Upgrowth localised | minor | minor | minor | no | minor | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | yes | no | | | | |
| | 2 | Arable headland/field edge | grass | grass | track | no | grass | | | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | no | | | | |
| | 4 | Surfaced (tarmac, stone etc) | grass | grass | gravel | mud | grass | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | na | na | tracked | na | | | | |
| | 2 | Headland (field edge) ploughed | no | no | no | na | no | | | | |
| | 3 | Path surface damaged/broken up | no | no | no | ploughed | no | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | no | no | V wet | no | | | | |
| | 5 | Upgrowth (on pathway) | minor | minor | none | none | minor | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | minor | minor | none | none | none | | | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | no | no | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | no | no | | | | |
| | 4 | Intimidating beast/person | no | no | no | no | no | | | | |
| | 5 | Collapsed wall | no | no | no | no | no | | | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | no | no | | | | |
| | 7 | Quarrying or extraction | no | no | no | no | no | | | | |
| | 8 | Plantation for forestry | no | no | no | no | no | | | | |

| key | | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--------------------------|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

Fingerpost at start is good, waymarker post at leg2 is loose and leaning. No waymarker post found at leg3 but suggest it is placed as track splits on to private ground. Crossfield ploughed out but tracked (straightlineing past next WM). Last leg is good and foot bridge ok (waymarkers could be updated).

Footbridge not DDA compliant.

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP5C n/a 18/02/18 wet Willow End Field |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0780 3149 | 0779 3150 | 0772 3178 | | | | | |
|----------------------------|--------------------------------|-------------------------------------|----------|--------------|--------------|--------------|--|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | good | none | none | | | | | | |
| | 2 | Waymark/other sign along path | no | replace | replace | | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | no | | | | | | |
| | 4 | Steps/revetment | no | no | no | | | | | | |
| | 5 | Bridges (length in meters) | no | no | no | | | | | | |
| | 6 | Styles | no | no | no | | | | | | |
| | 7 | Gates | no | CG | no | | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | | | | | | | |
| | 2 | Tree/brough | no | no | | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | | | | | | | |
| | 4 | Illegal or misleading sign | no | no | | | | | | | |
| | 5 | Building or structure | no | no | | | | | | | |
| | 6 | Muddy/boggy localised | no | muddy | | | | | | | |
| | 7 | Upgrowth localised | no | no | | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | ploughed | | | | | | | |
| | 2 | Arable headland/field edge | pavement | no | | | | | | | |
| | 3 | Natural/set-aside but not above | no | no | | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | tarmac | mud | | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | ploughed | | | | | | | |
| | 2 | Headland (field edge) ploughed | no | no | | | | | | | |
| | 3 | Path surface damaged/broken up | no | no | | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | boggy | | | | | | | |
| | 5 | Upgrowth (on pathway) | minor | no | | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | minor | minor | | | | | | | |
| | 2 | Standing water (pool/pond/lake) | no | no | | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | | | | | | | |
| | 4 | Intimidating beast/person | no | no | | | | | | | |
| | 5 | Collapsed wall | no | no | | | | | | | |
| | 6 | Encroachment (not by ploughing) | no | no | | | | | | | |
| | 7 | Quarrying or extraction | no | no | | | | | | | |
| | 8 | Plantation for forestry | no | no | | | | | | | |

| key | Summary of work required | | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|--------------------------|--|---|
| G | Good | Fingerpost at start is good but not at FP start. Waymarker post at leg2 missing, waymarker post at leg3 rotten through and laying on the ground requiring replacement. Light overgroth and some low hanging tree branches in places, track wet and slippery. Crush gate at leg2 is narrow for able body walkers. | |
| M | Missing | | |
| A | Attention | This section of FP5 is not DDA compliant, as the crush gate at leg2 is too narrow and path ploughed out. | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP6A n/a 22/03/18 wet Marriots Alley |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0819 3083 | 0827 3083 | 0827 3087 | 0827 3093 | 0829 3103 | 0837 3112 | 0852 3118 | 0862 3113 |
|--|--------------------------------|-------------------------------------|----|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | new | none | none | damaged | none | good | location | good |
| | 2 | Waymark/other sign along path | | none | none | none | none | none | none | none | none |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | no | no | no | no | no |
| | 4 | Steps/revetment | | no | no | no | no | no | no | no | no |
| | 5 | Bridges (length in meters) | | no | no | no | no | no | no | no | no |
| | 6 | Styles | | no | no | no | no | no | no | no | no |
| | 7 | Gates | | no | no | no | no | no | no | no | no |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | no | no | no | no | no | |
| | 2 | Tree/brough | | no | no | no | no | no | no | no | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | no | no | no | no | no | |
| | 4 | Illegal or misleading sign | | no | no | no | no | no | no | no | |
| | 5 | Building or structure | | no | no | no | no | no | no | no | |
| | 6 | Muddy/boggy localised | | no | no | no | no | no | no | no | |
| | 7 | Upgrowth localised | | no | no | no | no | no | no | no | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | no | no | no | no | no | |
| | 2 | Arable headland/field edge | | pavement | pavement | pavement | pavement | pavement | pavement | pavement | |
| | 3 | Natural/set-aside but not above | | no | no | no | no | no | no | no | |
| | 4 | Surfaced (tarmac, stone etc) | | tarmac | tarmac | tarmac | tarmac | tarmac | tarmac | tarmac | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E Q U I R E D | 1 | Cross field not reinstated | | na | na | na | na | na | na | na | |
| | 2 | Headland (field edge) ploughed | | na | na | no | na | no | no | no | |
| | 3 | Path surface damaged/broken up | | no | no | no | no | no | no | no | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | no | no | no | no | no | |
| | 5 | Upgrowth (on pathway) | | none | none | none | none | minor | none | minor | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | none | none | none | minor | minor | none | medium | |
| | 2 | Standing water (pool/pond/lake) | | no | no | no | no | no | no | no | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | no | no | no | no | no | |
| | 4 | Intimidating beast/person | | no | no | no | no | no | no | no | |
| | 5 | Collapsed wall | | no | no | no | no | no | no | no | |
| | 6 | Encroachment (not by ploughing) | | no | no | no | no | no | no | no | |
| | 7 | Quarrying or extraction | | no | no | no | no | no | no | no | |
| | 8 | Plantation for forestry | | no | no | no | no | no | no | no | |

| key | | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--------------------------|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

Fingerpost at start is new, no waymarker or finger post at leg2 start and missing at Leg3, damaged at leg4.
Leg4 and leg5 have minor overgroth however leg7 has more with restricted hight and width.
This section of FP6 is not DDA compliant, due to path width (overgroth) legs5 and leg7.

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged **no** Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP6B n/a 22/03/18 wet Dunstall Way |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0827 3083 | 0831 3080 | | | | | | |
|----------------------------|--------------------------------|-------------------------------------|----|--------------|--------------|--|--|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | none | good | | | | | | |
| | 2 | Waymark/other sign along path | | none | none | | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | | | | | | |
| | 4 | Steps/revetment | | no | no | | | | | | |
| | 5 | Bridges (length in meters) | | no | no | | | | | | |
| | 6 | Styles | | no | no | | | | | | |
| | 7 | Gates | | no | no | | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | | | | | | |
| | 2 | Tree/brough | | no | no | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | | | | | | |
| | 4 | Illegal or misleading sign | | no | no | | | | | | |
| | 5 | Building or structure | | no | no | | | | | | |
| | 6 | Muddy/boggy localised | | no | no | | | | | | |
| | 7 | Upgrowth localised | | no | no | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | | | | | | |
| | 2 | Arable headland/field edge | | pavement | pavement | | | | | | |
| | 3 | Natural/set-aside but not above | | no | no | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | tarmac | tarmac | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | na | na | | | | | | |
| | 2 | Headland (field edge) ploughed | | na | na | | | | | | |
| | 3 | Path surface damaged/broken up | | no | no | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | | | | | | |
| | 5 | Upgrowth (on pathway) | | none | none | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | none | none | | | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | no | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | | | | | | |
| | 4 | Intimidating beast/person | | no | no | | | | | | |
| | 5 | Collapsed wall | | no | no | | | | | | |
| | 6 | Encroachment (not by ploughing) | | no | no | | | | | | |
| | 7 | Quarrying or extraction | | no | no | | | | | | |
| | 8 | Plantation for forestry | | no | no | | | | | | |

| key | | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--------------------------|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

Fingerpost or waymarker at leg1start is missing, finger post at leg2 start is new and good. Minor overgroth however insufficient to restricted hight and width.
This section of FP6 is DDA compliant.

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged **no** Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|------------------|--------|----------------------|--------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP7A n/a 06/04/18 wet Bull Meadow |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | TL | 0810 3110 | 0810 3110 | 0800 3110 | 0800 3100 | 0790 3100 | 0770 3100 | 0770 3100 | |
|--------------------------------|-------------------------------|-------------------------------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--|
| 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | Missing | none | none | none | none | none | Good | |
| | 2 | Waymark/other sign along path | no | missing | missing | missing | missing | faded | no | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | no | no | no | no | no | |
| | 4 | Steps/revetment | no | no | no | no | no | no | no | |
| | 5 | Bridges (length in meters) | no | no | no | no | no | no | no | |
| | 6 | Styles | no | no | no | no | no | no | no | |
| | 7 | Gates | no | no | no | no | no | no | no | |
| 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | no | no | no | | |
| | 2 | Tree/brough | no | no | no | no | no | no | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | no | no | | |
| | 4 | Illegal or misleading sign | no | no | no | no | no | no | | |
| | 5 | Building or structure | no | no | no | no | no | no | | |
| | 6 | Muddy/boggy localised | no | no | no | no | no | no | | |
| | 7 | Upgrowth localised | no | no | no | no | no | no | | |
| 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | no | no | no | | |
| | 2 | Arable headland/field edge | no | no | no | no | no | no | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | no | no | | |
| | 4 | Surfaced (tarmac, stone etc) | tarmac | tarmac | tarmac | tarmac | tarmac | tarmac | | |
| 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | na | na | na | na | na | | |
| | 2 | Headland (field edge) ploughed | no | ok | no | na | no | no | | |
| | 3 | Path surface damaged/broken up | no | no | no | no | no | no | | |
| | 4 | Flooded/rutted/boggy/muddy | no | no | no | no | no | no | | |
| | 5 | Upgrowth (on pathway) | none | none | none | none | none | none | | |
| 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | none | none | none | none | none | major | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | no | no | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | no | no | | | |
| | 4 | Intimidating beast/person | no | no | no | no | no | | | |
| | 5 | Collapsed wall | no | no | no | no | no | | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | no | no | | | |
| | 7 | Quarrying or extraction | no | no | no | no | no | | | |
| | 8 | Plantation for forestry | no | no | no | no | no | | | |

| key | | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--------------------------|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP7B n/a 06/04/18 wet Brook End Green |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0770 3100 | 0770 3100 | 0750 3090 | 0740 3090 | 0720 3100 | | | |
|----------------------------|--------------------------------|-------------------------------------|------------|--------------|--------------|--------------|--------------|--------------|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | Good | none | none | none | none | none | | | |
| | 2 | Waymark/other sign along path | no | damaged | good | good | faded | | | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | no | no | no | no | | | |
| | 4 | Steps/revetment | replace | no | no | no | no | no | | | |
| | 5 | Bridges (length in meters) | no | 6mts | no | no | no | no | | | |
| | 6 | Styles | no | no | no | no | no | no | | | |
| | 7 | Gates | no | no | no | KGx2 | no | no | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | no | | | | | |
| | 2 | Tree/brough | no | no | no | no | | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | | | | | |
| | 4 | Illegal or misleading sign | no | no | no | no | | | | | |
| | 5 | Building or structure | no | no | no | no | | | | | |
| | 6 | Muddy/boggy localised | muddy | field | very | very | | | | | |
| | 7 | Upgrowth localised | minor | minor | minor | no | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | no | | | | | |
| | 2 | Arable headland/field edge | field edge | no | headland | grazing | | | | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | mud/grass | Mud/grass | grass | grass | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | ploughed | na | na | | | | | |
| | 2 | Headland (field edge) ploughed | no | ok | no | na | | | | | |
| | 3 | Path surface damaged/broken up | no | ploughed | minor | no | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | muddy | V muddy | V wet | | | | | |
| | 5 | Upgrowth (on pathway) | minor | none | none | none | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | medium | minor | none | none | | | | | |
| | 2 | Standing water (pool/pond/lake) | no | light | light | pooled | | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | no | | | | | |
| | 4 | Intimidating beast/person | no | no | no | no | | | | | |
| | 5 | Collapsed wall | no | no | no | no | | | | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | no | | | | | |
| | 7 | Quarrying or extraction | no | no | no | no | | | | | |
| | 8 | Plantation for forestry | no | no | no | no | | | | | |

| key | | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--------------------------|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

Steps adjacent to A6 bypass need replacing, waymarkers at leg2 need replacing and a waymarker post made more visible from a distance. Cross field pathis ploughed out and not reienstated, additional waymarker may be required. Both kissing gates are good but not highlighted only waymarked.

All Kissing Gates and foot bridge are not DDA compliant.

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP7C n/a 23/03/18 Franklin Avenue |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0798 3121 | 0799 3110 | | | | | | |
|----------------------------|--------------------------------|-------------------------------------|----|--------------|--------------|--|--|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | missing | missing | | | | | | |
| | 2 | Waymark/other sign along path | | none | none | | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | | | | | | |
| | 4 | Steps/revetment | | no | no | | | | | | |
| | 5 | Bridges (length in meters) | | no | no | | | | | | |
| | 6 | Styles | | no | no | | | | | | |
| | 7 | Gates | | no | no | | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | | | | | | | |
| | 2 | Tree/brough | | no | | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | | | | | | | |
| | 4 | Illegal or misleading sign | | no | | | | | | | |
| | 5 | Building or structure | | no | | | | | | | |
| | 6 | Muddy/boggy localised | | no | | | | | | | |
| | 7 | Upgrowth localised | | none | | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | | | | | | | |
| | 2 | Arable headland/field edge | | pavement | | | | | | | |
| | 3 | Natural/set-aside but not above | | no | | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | tarmac | | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | no | | | | | | | |
| | 2 | Headland (field edge) ploughed | | no | | | | | | | |
| | 3 | Path surface damaged/broken up | | no | | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | | | | | | | |
| | 5 | Upgrowth (on pathway) | | none | | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | none | | | | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | | | | | | | |
| | 4 | Intimidating beast/person | | no | | | | | | | |
| | 5 | Collapsed wall | | no | | | | | | | |
| | 6 | Encroachment (not by ploughing) | | no | | | | | | | |
| | 7 | Quarrying or extraction | | no | | | | | | | |
| | 8 | Plantation for forestry | | no | | | | | | | |

| key | | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--------------------------|--|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP7D n/a 23/03/18 Franklin Passage |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| GRID REFERENCE & MAP POINT | | TL | 0808 3113 | 0799 3117 | | | | | |
|--------------------------------|---|-------------------------------------|--------------|--------------|--|--|--|--|--|
| 1: PATH FURNITURE | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | missing | missing | | | | | |
| | 2 | Waymark/other sign along path | none | no | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | | | | | |
| | 4 | Steps/revetment | no | no | | | | | |
| | 5 | Bridges (length in meters) | no | no | | | | | |
| | 6 | Styles | no | no | | | | | |
| | 7 | Gates | no | no | | | | | |
| 2: OBSTRUCTIONS | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | | | | | | |
| | 2 | Tree/brough | no | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | | | | | | |
| | 4 | Illegal or misleading sign | no | | | | | | |
| | 5 | Building or structure | no | | | | | | |
| | 6 | Muddy/boggy localised | no | | | | | | |
| | 7 | Upgrowth localised | none | | | | | | |
| 3: SURFACE TYPE | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | | | | | | |
| | 2 | Arable headland/field edge | pavement | | | | | | |
| | 3 | Natural/set-aside but not above | no | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | tarmac | | | | | | |
| 4: OBSTRUCTIONS SURFACE | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | no | | | | | | |
| | 2 | Headland (field edge) ploughed | no | | | | | | |
| | 3 | Path surface damaged/broken up | no | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | | | | | | |
| | 5 | Upgrowth (on pathway) | none | | | | | | |
| 5: OBSTRUCTIONS | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | none | | | | | | |
| | 2 | Standing water (pool/pond/lake) | no | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | | | | | | |
| | 4 | Intimidating beast/person | no | | | | | | |
| | 5 | Collapsed wall | no | | | | | | |
| | 6 | Encroachment (not by ploughing) | no | | | | | | |
| | 7 | Quarrying or extraction | no | | | | | | |
| | 8 | Plantation for forestry | no | | | | | | |

| | | |
|-----|---------------------------------|---|
| key | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | |
| M | Missing | |
| A | Attention | |
| R | Repair/replace | |

No signage on this route, all pavement.
Footpath is DDA compliant.

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded yes Route GPS logged no Map attached and ammended yes

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP8 n/a 23/03/18 wet Mill Race Path |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0778 3147 | 0768 3123 | 0766 3101 | 0761 3081 | 0760 3078 | 0757 3077 | 0760 3065 | 0764 3043 |
|----------------------------|--------------------------------|-------------------------------------|----|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | good | good | none | none | new | new | missing | missing |
| | 2 | Waymark/other sign along path | | none | none | damaged | 2x good | none | good | none | none |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | no | no | no | no | no |
| | 4 | Steps/revetment | | no | no | no | 21 | no | 24 | no | no |
| | 5 | Bridges (length in meters) | | no | no | 5m | no | no | 1 narrow | no | no |
| | 6 | Styles | | no | no | no | no | no | no | 1x ok | no |
| | 7 | Gates | | security | 1x KG | no | no | no | no | no | no |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | no | no | no | no | no | |
| | 2 | Tree/brough | | no | no | minor | no | no | no | no | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | no | no | no | no | no | |
| | 4 | Illegal or misleading sign | | security | no | no | no | no | no | no | |
| | 5 | Building or structure | | no | no | no | no | no | no | no | |
| | 6 | Muddy/boggy localised | | no | no | minor | no | no | no | no | |
| | 7 | Upgrowth localised | | no | minor | minor | minor | no | minor | no | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | no | no | no | no | pasture | |
| | 2 | Arable headland/field edge | | driveway | headland | no | no | highway | no | no | |
| | 3 | Natural/set-aside but not above | | no | no | natural | natural | no | natural | no | |
| | 4 | Surfaced (tarmac, stone etc) | | gravel | gravel | grass | grass | tarmac | grass | grass | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | na | na | na | na | na | na | na | |
| | 2 | Headland (field edge) ploughed | | na | no | no | na | no | no | no | |
| | 3 | Path surface damaged/broken up | | no | no | no | no | no | no | no | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | no | no | no | no | no | |
| | 5 | Upgrowth (on pathway) | | none | minor | minor | none | na | minor | no | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | none | minor | minor | minor | na | minor | no | |
| | 2 | Standing water (pool/pond/lake) | | no | no | no | no | no | no | no | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | no | no | no | no | no | |
| | 4 | Intimidating beast/person | | no | no | no | no | no | no | no | |
| | 5 | Collapsed wall | | no | no | no | no | no | no | no | |
| | 6 | Encroachment (not by ploughing) | | no | no | no | no | no | no | no | |
| | 7 | Quarrying or extraction | | no | no | no | no | no | no | no | |
| | 8 | Plantation for forestry | | no | no | no | no | no | no | no | |

| key | | Summary of work required | Added to ViewRanger data base <div>yes - no</div> BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |
| | | Fingerpost at start is ok but a security gate outside trading hours will block access, finger post at leg2 start is good.KG at leg2 is not radar, junction with FP11 not marked. Bridge WM's damaged. Steps at Leg4 need attention. No signage at leg7 and leg8 (access questionable). | |
| | | FP8 is not DDA compliant, due to KG, style, steps and bridge width. | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP9 n/a 25/03/18 Longcroft Passage |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0788 3091 | 0789 3084 | | | | | | |
|----------------------------|--------------------------------|-------------------------------------|----|--------------|--------------|--|--|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | missing | good | | | | | | |
| | 2 | Waymark/other sign along path | | no | no | | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | | | | | | |
| | 4 | Steps/revetment | | no | no | | | | | | |
| | 5 | Bridges (length in meters) | | no | no | | | | | | |
| | 6 | Styles | | no | no | | | | | | |
| | 7 | Gates | | no | no | | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | | | | | | | |
| | 2 | Tree/brough | | no | | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | | | | | | | |
| | 4 | Illegal or misleading sign | | no | | | | | | | |
| | 5 | Building or structure | | no | | | | | | | |
| | 6 | Muddy/boggy localised | | no | | | | | | | |
| | 7 | Upgrowth localised | | none | | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | | | | | | | |
| | 2 | Arable headland/field edge | | no | | | | | | | |
| | 3 | Natural/set-aside but not above | | no | | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | tm/grass | | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | no | | | | | | | |
| | 2 | Headland (field edge) ploughed | | no | | | | | | | |
| | 3 | Path surface damaged/broken up | | no | | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | | | | | | | |
| | 5 | Upgrowth (on pathway) | | none | | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | none | | | | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | | | | | | | |
| | 4 | Intimidating beast/person | | no | | | | | | | |
| | 5 | Collapsed wall | | no | | | | | | | |
| | 6 | Encroachment (not by ploughing) | | no | | | | | | | |
| | 7 | Quarrying or extraction | | no | | | | | | | |
| | 8 | Plantation for forestry | | no | | | | | | | |

| key | | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--------------------------|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

Fingerpost at Leg1 start is missing, path is in good condition and no obstructions. Fingerpost at end of leg is good.
Footpath is DDA compliant.

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP10 n/a 25/03/18 Mill Field path |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0755 3166 | 0745 3138 | 0742 3131 | 0740 3118 | | | | |
|----------------------------|--------------------------------|-------------------------------------|----------|--------------|--------------|--------------|--------------|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | Good | none | none | none | | | | | |
| | 2 | Waymark/other sign along path | good | missing | missing | missing | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | repair | no | no | no | | | | | |
| | 4 | Steps/revetment | no | no | no | no | | | | | |
| | 5 | Bridges (length in meters) | n'row 1m | n'row 1m | no | no | | | | | |
| | 6 | Styles | no | no | no | no | | | | | |
| | 7 | Gates | no | no | no | no | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | | | | | | |
| | 2 | Tree/brough | no | minor | no | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | | | | | | |
| | 4 | Illegal or misleading sign | no | no | no | | | | | | |
| | 5 | Building or structure | no | no | no | | | | | | |
| | 6 | Muddy/boggy localised | no | minor | no | | | | | | |
| | 7 | Upgrowth localised | minor | minor | minor | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | ploughed | no | no | | | | | | |
| | 2 | Arable headland/field edge | no | no | headland | | | | | | |
| | 3 | Natural/set-aside but not above | no | no | no | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | mud | mud/grass | grass | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | ploughed | na | na | | | | | | |
| | 2 | Headland (field edge) ploughed | no | na | no | | | | | | |
| | 3 | Path surface damaged/broken up | ploughed | no | no | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | no | minor | | | | | | |
| | 5 | Upgrowth (on pathway) | none | minor | minor | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | none | medium | no | | | | | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | | | | | | |
| | 4 | Intimidating beast/person | no | no | no | | | | | | |
| | 5 | Collapsed wall | no | no | no | | | | | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | | | | | | |
| | 7 | Quarrying or extraction | no | no | no | | | | | | |
| | 8 | Plantation for forestry | no | no | no | | | | | | |

| | | |
|-----|---------------------------------|---|
| key | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | |
| M | Missing | |
| A | Attention | |
| R | Repair/replace | |

Fingerpost at Leg1 start is good, bridge is narrow and has no hand rail, pedestrian chicane is in need of repair (or removal). Crossfield path is ploughed out and not reinstated.Waymarker at leg2 is missing as with leg3. Bridge at end of leg2 is narrow and has no waymarker. Waymarker post at end of leg3 is missing.
Footpath is not DDA compliant due to bridge width and narrow pedestrian chicane.

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|------------------|--------|----------------------|--------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP11 section A 06/04/18 wet Sharpenhoe Way |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | TL | 0767 3124 | 0763 3121 | 0740 3118 | 0734 3118 | 0719 3118 | 0710 3119 | | |
|----------------------------|--------------------------------|-------------------------------------|--------------|--------------|--------------|--------------|--------------|--------------|--|--|
| | 1: PATH FURNITURE | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | good | none | none | damaged | none | good | | |
| | 2 | Waymark/other sign along path | none | good | none | none | x2 ok | none | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | no | no | no | no | | |
| | 4 | Steps/revetment | no | no | no | no | no | no | | |
| | 5 | Bridges (length in meters) | no | no | no | narrow | no | no | | |
| | 6 | Styles | no | no | no | no | no | no | | |
| | 7 | Gates | no | 1x KG | no | 1x KG | 1x KG | 1x KG | | |
| | 2: OBSTRUCTIONS | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | no | no | no | | |
| | 2 | Tree/brough | no | minor | no | no | no | no | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | no | no | | |
| | 4 | Illegal or misleading sign | no | no | no | no | no | no | | |
| | 5 | Building or structure | no | no | no | no | no | no | | |
| | 6 | Muddy/boggy localised | no | no | no | minor | no | no | | |
| | 7 | Upgrowth localised | no | no | no | minor | no | no | | |
| | 3: SURFACE TYPE | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | no | no | no | | |
| | 2 | Arable headland/field edge | pavement | headland | track | track | grazing | headland | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | no | no | | |
| | 4 | Surfaced (tarmac, stone etc) | gravel | grass | grass | grass | grass | grass | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | na | na | na | na | na | | |
| | 2 | Headland (field edge) ploughed | na | no | no | na | no | no | | |
| | 3 | Path surface damaged/broken up | no | no | no | no | no | no | | |
| | 4 | Flooded/rutted/boggy/muddy | no | minor | no | no | no | no | | |
| | 5 | Upgrowth (on pathway) | none | none | none | minor | minor | minor | | |
| | 5: OBSTRUCTIONS | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | none | none | none | minor | minor | minor | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | no | no | no | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | no | no | no | | |
| | 4 | Intimidating beast/person | no | no | no | no | no | no | | |
| | 5 | Collapsed wall | no | no | no | no | no | no | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | no | no | no | | |
| | 7 | Quarrying or extraction | no | no | no | no | no | no | | |
| | 8 | Plantation for forestry | no | no | no | no | no | no | | |

| key | | Summary of work required Fingerpost at start is new, KG atleg2 old spec but ok. Waymarker post missing at leg3 (FP junction) and post rotten and on ground at leg4. KG at leg4, leg5 and leg6 new (non RADAR), bridge at leg4 narrow. ROW blocked at leg7 by get hedge and fallen tree branches. FP11 is not DDA compliant, due to all KG's width, and narrow bridges at legs4 and leg10. | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|------------------|--------|----------------------|--------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP11 section B 06/04/18 wet Sharpenhoe Way |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | TL | 0710 3119 | 0661 3119 | 0660 3126 | 0628 3130 | 0623 3129 | | | |
|----------------------------|--------------------------------|-------------------------------------|--------------|--------------|--------------|--------------|--------------|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | good | none | none | none | none | | | |
| | 2 | Waymark/other sign along path | none | good | good | none | x2 ok | | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | no | no | no | | | |
| | 4 | Steps/revetment | no | no | no | no | no | | | |
| | 5 | Bridges (length in meters) | no | no | no | narrow | no | | | |
| | 6 | Styles | no | no | no | no | no | | | |
| | 7 | Gates | no | no | no | no | no | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | no | | | | |
| | 2 | Tree/brough | blocked | minor | no | no | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | | | | |
| | 4 | Illegal or misleading sign | no | no | no | no | | | | |
| | 5 | Building or structure | no | no | no | no | | | | |
| | 6 | Muddy/boggy localised | no | no | no | minor | | | | |
| | 7 | Upgrowth localised | blocked | no | minor | minor | | | | |
| | 3: SURFACE TYPE | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | yes | | | | |
| | 2 | Arable headland/field edge | headland | headland | track | track | | | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | | | | |
| | 4 | Surfaced (tarmac, stone etc) | grass | grass | grass | grass | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | na | na | good | | | | |
| | 2 | Headland (field edge) ploughed | no | no | no | na | | | | |
| | 3 | Path surface damaged/broken up | no | no | no | no | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | minor | no | no | | | | |
| | 5 | Upgrowth (on pathway) | major | none | minor | no | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | major | none | minor | no | | | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | no | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | no | | | | |
| | 4 | Intimidating beast/person | no | no | no | no | | | | |
| | 5 | Collapsed wall | no | no | no | no | | | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | no | | | | |
| | 7 | Quarrying or extraction | no | no | no | no | | | | |
| | 8 | Plantation for forestry | no | no | no | no | | | | |

| key | | Summary of work required Fingerpost at start is new, KG atleg2 old spec but ok. Waymarker post missing at leg3 (FP junction) and post rotten and on ground at leg4. KG at leg4, leg5 and leg6 new (non RADAR), bridge at leg4 narrow. ROW blocked at leg7 by get hedge and fallen tree branches. FP11 is not DDA compliant, due to all KG's width, and narrow bridges at legs4 and leg10. | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP12A 25/03/18 wet Barton Road path |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | TL | 0728 3071 | 0733 3061 | | | | | | |
|----------------------------|--------------------------------|-------------------------------------|--------------|--------------|--|--|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | missing | none | | | | | | |
| | 2 | Waymark/other sign along path | none | none | | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | | | | | | |
| | 4 | Steps/revetment | no | no | | | | | | |
| | 5 | Bridges (length in meters) | no | no | | | | | | |
| | 6 | Styles | poor | no | | | | | | |
| | 7 | Gates | no | no | | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | yes | | | | | | | |
| | 2 | Tree/brough | no | | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | | | | | | | |
| | 4 | Illegal or misleading sign | no | | | | | | | |
| | 5 | Building or structure | no | | | | | | | |
| | 6 | Muddy/boggy localised | no | | | | | | | |
| | 7 | Upgrowth localised | minor | | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | | | | | | | |
| | 2 | Arable headland/field edge | paddock | | | | | | | |
| | 3 | Natural/set-aside but not above | no | | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | grass | | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | | | | | | | |
| | 2 | Headland (field edge) ploughed | no | | | | | | | |
| | 3 | Path surface damaged/broken up | no | | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | | | | | | | |
| | 5 | Upgrowth (on pathway) | minor | | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | minor | | | | | | | |
| | 2 | Standing water (pool/pond/lake) | no | | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | | | | | | | |
| | 4 | Intimidating beast/person | no | | | | | | | |
| | 5 | Collapsed wall | no | | | | | | | |
| | 6 | Encroachment (not by ploughing) | no | | | | | | | |
| | 7 | Quarrying or extraction | no | | | | | | | |
| | 8 | Plantation for forestry | no | | | | | | | |

| | | | |
|-----|----------------|--|---|
| key | | Summary of work required Fingerpost at start is missing it's finger. The associated style is poor (and non RADAR/ DDA compliant), Leg1 is also blocked by several field fences (paddock) before its end which is unmarked and indeterminate. | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | FP12A is not DDA compliant, due to a style at Leg1 start (end indertmind). | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded yes Route GPS logged no Map attached and ammended yes

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP12B 25/03/18 wet Horslers Field |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0743 3074 | 0748 3059 | 0759 3049 | | | | | |
|---|--------------------------------|-------------------------------------|----|--------------|--------------|--------------|--|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | good | none | none | | | | | |
| | 2 | Waymark/other sign along path | | none | none | none | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | | | | | |
| | 4 | Steps/revetment | | no | no | no | | | | | |
| | 5 | Bridges (length in meters) | | no | no | no | | | | | |
| | 6 | Styles | | no | no | no | | | | | |
| | 7 | Gates | | locked | no | no | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | yes | yes | | | | | | |
| | 2 | Tree/brough | | no | no | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | | | | | | |
| | 4 | Illegal or misleading sign | | no | no | | | | | | |
| | 5 | Building or structure | | no | no | | | | | | |
| | 6 | Muddy/boggy localised | | no | no | | | | | | |
| | 7 | Upgrowth localised | | no | no | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | | | | | | |
| | 2 | Arable headland/field edge | | paddock | paddock | | | | | | |
| | 3 | Natural/set-aside but not above | | no | no | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | grass | grass | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R | 1 | Cross field not reinstated | | na | na | | | | | | |
| | 2 | Headland (field edge) ploughed | | no | no | | | | | | |
| | 3 | Path surface damaged/broken up | | no | no | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | | | | | | |
| | 5 | Upgrowth (on pathway) | | no | no | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| E Q U I P M E N T | 1 | Overgrowth (eg hedge beside path) | | no | no | | | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | no | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | | | | | | |
| | 4 | Intimidating beast/person | | no | no | | | | | | |
| | 5 | Collapsed wall | | no | no | | | | | | |
| | 6 | Encroachment (not by ploughing) | | no | no | | | | | | |
| | 7 | Quarrying or extraction | | no | no | | | | | | |
| | 8 | Plantation for forestry | | no | no | | | | | | |

| | | |
|------------------|--|---|
| key | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G Good | Fingerpost at start is good. The associated field gate is locked and non RADAR/ DDA compliant), Leg1 is also blocked by several field fences (paddock) before its end which is unmarked and indeterminate. | |
| M Missing | | |
| A Attention | FP12B is not DDA compliant, due to a gate at Leg1 start (end indertmind). | |
| R Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP12C 25/03/18 wet Unity Hall Path |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0795 3083 | 0795 3080 | 0786 3079 | 0787 3076 | 0770 3073 | | | |
|----------------------------|--------------------------------|-------------------------------------|--------|--------------|--------------|--------------|--------------|--------------|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | good | none | none | none | none | none | | | |
| | 2 | Waymark/other sign along path | none | none | none | none | none | none | | | |
| | 3 | Safety/amenity barrier eg.cycle | no | no | no | no | no | no | | | |
| | 4 | Steps/revetment | no | no | no | no | no | no | | | |
| | 5 | Bridges (length in meters) | no | no | no | no | no | no | | | |
| | 6 | Styles | no | no | no | no | no | no | | | |
| | 7 | Gates | no | no | no | no | no | no | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | yes | yes | yes | yes | | | | | |
| | 2 | Tree/brough | no | no | no | no | | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | | | | | |
| | 4 | Illegal or misleading sign | no | no | no | no | | | | | |
| | 5 | Building or structure | no | no | no | no | | | | | |
| | 6 | Muddy/boggy localised | no | no | no | no | | | | | |
| | 7 | Upgrowth localised | no | no | no | no | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | no | | | | | |
| | 2 | Arable headland/field edge | path | paddock | paddock | paddock | | | | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | tarmac | grass | grass | grass | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | na | na | na | | | | | |
| | 2 | Headland (field edge) ploughed | no | no | no | no | | | | | |
| | 3 | Path surface damaged/broken up | no | no | no | no | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | no | no | no | | | | | |
| | 5 | Upgrowth (on pathway) | no | no | no | no | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | no | no | no | no | | | | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | no | | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | no | | | | | |
| | 4 | Intimidating beast/person | no | no | no | no | | | | | |
| | 5 | Collapsed wall | no | no | no | no | | | | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | no | | | | | |
| | 7 | Quarrying or extraction | no | no | no | no | | | | | |
| | 8 | Plantation for forestry | no | no | no | no | | | | | |

| | | | |
|-----|---------------------------------|--|---|
| key | Summary of work required | | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | Fingerpost at start is good. The associated path is blocked and is unmarked and indeterminate. | |
| M | Missing | FP12C is not DDA compliant, due to a no access. | |
| A | Attention | | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP12D 25/03/18 wet Searchlight Field |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0761 3080 | 0761 3083 | 0739 3094 | 0737 3094 | | | | |
|----------------------------|--------------------------------|-------------------------------------|----|--------------|--------------|--------------|--------------|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | none | none | none | none | | | | |
| | 2 | Waymark/other sign along path | | good | none | good | good | | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | no | | | | |
| | 4 | Steps/revetment | | no | no | no | no | | | | |
| | 5 | Bridges (length in meters) | | no | no | no | no | | | | |
| | 6 | Styles | | no | no | no | no | | | | |
| | 7 | Gates | | no | no | no | 1x KG | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | no | | | | | |
| | 2 | Tree/brough | | no | no | no | | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | no | | | | | |
| | 4 | Illegal or misleading sign | | no | no | no | | | | | |
| | 5 | Building or structure | | no | no | no | | | | | |
| | 6 | Muddy/boggy localised | | minor | minor | no | | | | | |
| | 7 | Upgrowth localised | | minor | no | no | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | yes | no | | | | | |
| | 2 | Arable headland/field edge | | no | no | no | | | | | |
| | 3 | Natural/set-aside but not above | | no | no | no | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | grass | ploughed | grass | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | na | ploughed | na | | | | | |
| | 2 | Headland (field edge) ploughed | | no | no | no | | | | | |
| | 3 | Path surface damaged/broken up | | no | no | no | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | no | | | | | |
| | 5 | Upgrowth (on pathway) | | minor | none | none | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | minor | none | none | | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | no | no | | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | no | | | | | |
| | 4 | Intimidating beast/person | | no | no | no | | | | | |
| | 5 | Collapsed wall | | no | no | no | | | | | |
| | 6 | Encroachment (not by ploughing) | | no | no | no | | | | | |
| | 7 | Quarrying or extraction | | no | no | no | | | | | |
| | 8 | Plantation for forestry | | no | no | no | | | | | |

| | | | |
|-----|---------------------------------|---|---|
| key | Summary of work required | | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | Waymarker post at start is good as is the last and second from last however post missing from Leg2 start. | |
| M | Missing | Cross field path has been ploughed out and not visably | |
| A | Attention | FP12D is DDA compliant. | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|------------------|--------|----------------------|--------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP13A n/a 23/03/18 wet Park Meadow |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | TL | 0768 3123 | 0773 3124 | 0777 3123 | 0776 3116 | 0785 3108 | | | |
|----------------------------|--------------------------------|-------------------------------------|--------------|--------------|--------------|--------------|--------------|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | good | none | good | none | none | | | |
| | 2 | Waymark/other sign along path | none | none | none | faded | none | | | |
| | 3 | Safety/amenity barrier eg.cycle | none | none | none | none | | | | |
| | 4 | Steps/revetment | none | attention | none | none | | | | |
| | 5 | Bridges (length in meters) | none | none | none | none | | | | |
| | 6 | Styles | none | none | none | none | | | | |
| | 7 | Gates | none | none | none | none | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | none | none | none | none | | | | |
| | 2 | Tree/brough | no | no | BLOCKED | no | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | | | | |
| | 4 | Illegal or misleading sign | no | no | no | no | | | | |
| | 5 | Building or structure | no | no | no | no | | | | |
| | 6 | Muddy/boggy localised | no | no | no | no | | | | |
| | 7 | Upgrowth localised | no | minor | MAJOR | no | | | | |
| | 3: SURFACE TYPE | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | no | | | | |
| | 2 | Arable headland/field edge | no | no | no | no | | | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | | | | |
| | 4 | Surfaced (tarmac, stone etc) | grass | tarmac | grass | tarmac | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | na | na | na | | | | |
| | 2 | Headland (field edge) ploughed | no | no | no | no | | | | |
| | 3 | Path surface damaged/broken up | no | no | no | no | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | no | no | no | | | | |
| | 5 | Upgrowth (on pathway) | none | none | MAJOR | none | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | no | no | MAJOR | minor | | | | |
| | 2 | Standing water (pool/pond/lake) | none | none | none | none | | | | |
| | 3 | Barbed wire/electric fence adjacent | none | none | none | none | | | | |
| | 4 | Intimidating beast/person | none | none | none | none | | | | |
| | 5 | Collapsed wall | none | none | none | none | | | | |
| | 6 | Encroachment (not by ploughing) | Yes | none | none | none | | | | |
| | 7 | Quarrying or extraction | none | none | none | none | | | | |
| | 8 | Plantation for forestry | none | none | none | none | | | | |

| key | | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|--------------------------|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|------------------|--------|----------------------|--------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP13B 04/04/18 wet Faldo Field |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0777 3199 | 0776 3199 | 0743 3249 | 0742 3250 | | | | |
|----------------------------|--------------------------------|-------------------------------------|----|--------------|--------------|--------------|--------------|--|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | none | none | none | none | | | | |
| | 2 | Waymark/other sign along path | | rotten | rotten | good | good | | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | no | | | | |
| | 4 | Steps/revetment | | no | no | no | no | | | | |
| | 5 | Bridges (length in meters) | | 1x 5mt | no | 1x1.5m | no | | | | |
| | 6 | Styles | | no | no | no | no | | | | |
| | 7 | Gates | | no | no | no | no | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | no | | | | | |
| | 2 | Tree/brough | | no | no | no | | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | no | | | | | |
| | 4 | Illegal or misleading sign | | no | no | no | | | | | |
| | 5 | Building or structure | | no | no | no | | | | | |
| | 6 | Muddy/boggy localised | | minor | minor | no | | | | | |
| | 7 | Upgrowth localised | | minor | no | medium | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | yes | no | | | | | |
| | 2 | Arable headland/field edge | | no | no | no | | | | | |
| | 3 | Natural/set-aside but not above | | no | no | no | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | mud | ploughed | grass | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | na | ploughed | na | | | | | |
| | 2 | Headland (field edge) ploughed | | no | no | no | | | | | |
| | 3 | Path surface damaged/broken up | | no | no | no | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | slippery | no | no | | | | | |
| | 5 | Upgrowth (on pathway) | | minor | none | minor | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | minor | none | medium | | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | no | no | | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | no | | | | | |
| | 4 | Intimidating beast/person | | no | no | no | | | | | |
| | 5 | Collapsed wall | | no | no | no | | | | | |
| | 6 | Encroachment (not by ploughing) | | no | no | no | | | | | |
| | 7 | Quarrying or extraction | | no | no | no | | | | | |
| | 8 | Plantation for forestry | | no | no | no | | | | | |

| | | | |
|-----|----------------|--|---|
| key | | Summary of work required Waymarker post at Jct with FP5 is rotten trough, bank down to bridge slippery (requires steps), Waymarker at Leg2 is rotten. Cross field path has been ploughed out and not visably. Waymarker post at Leg 3 and 4 ok. Culvert bridge at leg3 is narrow. Gap at leg3 could be opened more. FP13B is not DDA compliant due to bridge widths and ploughed out track.. | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP14A 04/04/18 wet Airfield Path |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0744 3170 | 0738 3152 | 0722 3157 | 0707 3176 | 0703 3175 | 0679 3180 | 0669 3179 | |
|----------------------------|--------------------------------|-------------------------------------|------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | missing | none | none | none | none | none | none | |
| | 2 | Waymark/other sign along path | | none | none | 2x good | none | none | faded | none | |
| | 3 | Safety/amenity barrier eg.cycle | fingerpost | | no | no | no | no | no | no | |
| | 4 | Steps/revetment | | no | no | 1x step | no | no | no | no | |
| | 5 | Bridges (length in meters) | | no | no | 1x5m | no | no | no | no | |
| | 6 | Styles | | no | no | no | no | no | no | no | |
| | 7 | Gates | | no | no | no | no | no | no | no | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | no | no | no | no | | |
| | 2 | Tree/brough | | no | no | minor | medium | no | no | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | no | no | no | no | | |
| | 4 | Illegal or misleading sign | | no | no | no | no | no | no | | |
| | 5 | Building or structure | | no | no | no | no | no | no | | |
| | 6 | Muddy/boggy localised | | minor | no | muddy | muddy | muddy | muddy | | |
| | 7 | Upgrowth localised | | minor | no | medium | major | no | minor | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | no | no | yes | no | | |
| | 2 | Arable headland/field edge | | no | no | yes | no | no | headland | | |
| | 3 | Natural/set-aside but not above | | no | no | no | planting | no | no | | |
| | 4 | Surfaced (tarmac, stone etc) | | grass | gravel | mud | grass | mud | grass | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | na | na | na | na | ploughed | no | | |
| | 2 | Headland (field edge) ploughed | | no | no | no | no | no | no | | |
| | 3 | Path surface damaged/broken up | | no | no | tree roots | no | ploughed | minor | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | uneven | no | ploughed | boggy | | |
| | 5 | Upgrowth (on pathway) | | minor | none | minor | no | no | minor | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | minor | none | medium | major | no | no | | |
| | 2 | Standing water (pool/pond/lake) | | no | no | no | minor | no | no | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | no | no | no | no | | |
| | 4 | Intimidating beast/person | | no | no | no | no | no | no | | |
| | 5 | Collapsed wall | | no | no | no | no | no | no | | |
| | 6 | Encroachment (not by ploughing) | | no | no | no | no | no | no | | |
| | 7 | Quarrying or extraction | | no | no | no | no | no | no | | |
| | 8 | Plantation for forestry | | no | no | no | yes | no | no | | |

| key | | Summary of work required Waymarker post at Leg1 is missing a finger, no waymarker at leg2. Bridge at Leg3 is good with 2 wm (but raised 1 step up?) Leg3 is poor, uneven and a trip hazard. LEG4 IS BLOCKED BY OVERGROWTH Cross field path at Leg5 has been ploughed out and not visibily. Waymarker post at Leg6 faded. No waymarker at end. This FP is gapped with PUL FP14 & STL FP36 FP14A is not DDA compliant due to bridge step, track surface, blockage and ploughed out track. | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
|-----|----------------|---|---|
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP14B 04/04/18 wet Airfield Path Link |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0738 3172 | 0727 3163 | 0726 3159 | 0723 3160 | 0722 3158 | | | |
|--|--------------------------------|-------------------------------------|----|--------------|--------------|--------------|--------------|--------------|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | missing | none | none | none | none | | | |
| | 2 | Waymark/other sign along path | | none | none | none | none | 2x good | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | no | no | | | |
| | 4 | Steps/revetment | | none | no | no | no | 1x step | | | |
| | 5 | Bridges (length in meters) | | no | no | no | no | 1x5m | | | |
| | 6 | Styles | | no | no | no | no | no | | | |
| | 7 | Gates | | no | no | no | no | no | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | no | no | | | | |
| | 2 | Tree/brough | | no | no | no | no | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | no | no | | | | |
| | 4 | Illegal or misleading sign | | no | no | no | no | | | | |
| | 5 | Building or structure | | no | no | no | no | | | | |
| | 6 | Muddy/boggy localised | | no | no | no | no | | | | |
| | 7 | Upgrowth localised | | no | no | no | no | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | no | no | | | | |
| | 2 | Arable headland/field edge | | no | no | no | no | | | | |
| | 3 | Natural/set-aside but not above | | no | no | no | no | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | grass | tarmac | tarmac | tarmac | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E Q U I R E D | 1 | Cross field not reinstated | | na | na | na | na | | | | |
| | 2 | Headland (field edge) ploughed | | no | no | no | no | | | | |
| | 3 | Path surface damaged/broken up | | soil bank | no | no | no | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | no | no | | | | |
| | 5 | Upgrowth (on pathway) | | minor | none | none | none | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | none | none | none | none | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | no | no | no | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | no | no | | | | |
| | 4 | Intimidating beast/person | | no | no | no | no | | | | |
| | 5 | Collapsed wall | | no | no | no | no | | | | |
| | 6 | Encroachment (not by ploughing) | | no | no | no | no | | | | |
| | 7 | Quarrying or extraction | | no | no | no | no | | | | |
| | 8 | Plantation for forestry | | no | no | no | no | | | | |

| | | | |
|-----|---------------------------------|---|---|
| key | Summary of work required | | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | Fingerpost at Leg1 is missing, no waymarkers at Legs 2,3, or 4.. Bridge at Leg5 is good with 2 wm (but raised 1 step up?) | |
| M | Missing | | |
| A | Attention | FP14B is not DDA compliant due to soil bank (on ramp or steps) and raised bridge step. | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP15A 20/03/18 wet Barton Springs |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0853 3031 | 0852 3028 | 0854 3016 | 0868 2972 | 0872 2960 | 0892 2927 | 0891 2924 | |
|--|--------------------------------|-------------------------------------|----|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--|
| | 1: PATH FURNITURE | | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | good | none | none | none | none | none | none | |
| | 2 | Waymark/other sign along path | | none | none | none | faded | faded | faded | none | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | no | no | no | no | |
| | 4 | Steps/revetment | | none | no | no | no | no | no | no | |
| | 5 | Bridges (length in meters) | | no | no | no | 4m good | no | no | no | |
| | 6 | Styles | | no | no | no | no | no | no | no | |
| | 7 | Gates | | no | radar KG | no | no | 2x KG | no | KG | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | no | no | no | no | | |
| | 2 | Tree/brough | | no | no | 2x | no | no | no | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | no | no | no | no | | |
| | 4 | Illegal or misleading sign | | no | no | no | no | no | no | | |
| | 5 | Building or structure | | no | no | no | no | no | no | | |
| | 6 | Muddy/boggy localised | | no | muddy | muddy | muddy | muddy | muddy | | |
| | 7 | Upgrowth localised | | no | minor | minor | minor | minor | minor | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | no | no | no | no | | |
| | 2 | Arable headland/field edge | | no | headland | headland | no | no | no | | |
| | 3 | Natural/set-aside but not above | | highway | no | no | natural | NNR | NNR | | |
| | 4 | Surfaced (tarmac, stone etc) | | gravel | mud | grass | mud | mud | mud | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E Q U I R E D | 1 | Cross field not reinstated | | na | na | na | na | na | na | | |
| | 2 | Headland (field edge) ploughed | | no | no | no | no | no | no | | |
| | 3 | Path surface damaged/broken up | | no | no | no | no | no | no | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | muddy | muddy | muddy | muddy | muddy | | |
| | 5 | Upgrowth (on pathway) | | no | minor | minor | minor | minor | minor | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | none | minor | minor | minor | minor | minor | | |
| | 2 | Standing water (pool/pond/lake) | | no | minor | minor | minor | minor | minor | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | no | no | no | no | | |
| | 4 | Intimidating beast/person | | no | no | no | no | no | no | | |
| | 5 | Collapsed wall | | no | no | no | no | no | no | | |
| | 6 | Encroachment (not by ploughing) | | no | no | no | no | no | no | | |
| | 7 | Quarrying or extraction | | no | no | no | no | no | no | | |
| | 8 | Plantation for forestry | | no | no | no | no | no | no | | |

| | | | |
|-----|---------------------------------|---|---|
| key | Summary of work required | | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | Fingerpost at Leg1 is good (location?), no waymarkers at Legs 2 and ,3. Wm on legs 4 and 5 faded. 2x tree branches down and path has rerouted round (off track). This path is bearily walkable due to extensive flooding and deep mud. End of Leg5 cross slope is slippery.Leg6 is not marked but required to link with BLC FP1 and BW16 (also not marked). | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | FP14B is not DDA compliant due to soil bank (on ramp or steps) and raised bridge step. | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|------------------|--------|----------------------|--------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP15B 16/03/18 wet Higgins Wood |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0728 3148 | 0721 3192 | 0720 3194 | 0721 3195 | 0716 3214 | 0711 3214 | 0693 3229 | |
|--|----------------------------|-------------------------------------|----|--------------|--------------|--------------|--------------|--------------|--------------|--------------|---|
| | 1: PATH FURNITURE | | | leg 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | Missing | Good | none | none | none | none | none | |
| | 2 | Waymark/other sign along path | | none | none | Good | Good | Missing | Missing | Nearby | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | no | no | no | no | |
| | 4 | Steps/revetment | | no | no | no | no | no | no | no | |
| | 5 | Bridges (length in meters) | | no | no | 4m Att Re | no | no | no | no | |
| | 6 | Styles | | no | no | no | no | no | no | no | |
| | 7 | Gates | | no | no | no | no | no | no | no | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | no | no | no | no | | |
| | 2 | Tree/brough | | no | no | no | no | no | no | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | no | no | no | no | | |
| | 4 | Illegal or misleading sign | | no | no | no | no | no | no | | |
| | 5 | Building or structure | | no | no | no | no | no | no | | |
| | 6 | Muddy/boggy localised | | no | no | no | no | no | no | | |
| | 7 | Upgrowth localised | | no | no | medium | no | no | no | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | no | cropped | cropped | no | | |
| | 2 | Arable headland/field edge | | no | no | no | no | no | no | | |
| | 3 | Natural/set-aside but not above | | no | no | no | no | no | no | | |
| | 4 | Surfaced (tarmac, stone etc) | | tarmac | Mud/grv | grass | cropped | cropped | grass | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E Q U I R E D | 1 | Cross field not reinstated | | na | no | no | unmarked | unmarked | no | | |
| | 2 | Headland (field edge) ploughed | | no | no | no | no | no | no | | |
| | 3 | Path surface damaged/broken up | | no | no | no | ploughed | ploughed | no | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | no | mud | mud | mud | | |
| | 5 | Upgrowth (on pathway) | | no | minor | none | none | none | minor | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | no | medium | minor | none | none | minor | | |
| | 2 | Standing water (pool/pond/lake) | | no | none | none | mud | mud | minor | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | no | no | no | no | | |
| | 4 | Intimidating beast/person | | no | no | no | no | no | no | | |
| | 5 | Collapsed wall | | no | no | no | no | no | no | | |
| | 6 | Encroachment (not by ploughing) | | no | no | no | no | no | no | | |
| | 7 | Quarrying or extraction | | no | no | no | no | no | no | | |
| | 8 | Plantation for forestry | | no | no | no | no | no | woodland | | |

| | | |
|------------------|---|--|
| key | Summary of work required | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G Good | FP not marked from road but far side of carpark. | |
| M Missing | Footbridge has severial boards rotten trough and is unsafe. Cross field parth un-reinstated and has no waymarkers for remainder of route. | |
| A Attention | Tempory maymarks and sign erected by farmer not to accepted PROW. | |
| R Repair/replace | FP15B is not DDA compliant due to bridge safety. | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP16 04/04/18 wet Stonley Wood |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0941 2844 | 0939 2862 | 0928 2951 | | | | | |
|----------------------------|-------------------------------|-------------------------------------|----|--------------|--------------|--------------|---|---|---|---|---|
| | 1: PATH FURNITURE | | | leg 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | good | none | none | | | | | |
| | 2 | Waymark/other sign along path | | none | none | none | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | | | | | |
| | 4 | Steps/revetment | | no | no | no | | | | | |
| | 5 | Bridges (length in meters) | | no | no | no | | | | | |
| | 6 | Styles | | no | no | no | | | | | |
| | 7 | Gates | | 1x CG | no | no | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | | | | | | |
| | 2 | Tree/brough | | no | no | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | | | | | | |
| | 4 | Illegal or misleading sign | | no | no | | | | | | |
| | 5 | Building or structure | | no | no | | | | | | |
| | 6 | Muddy/boggy localised | | no | no | | | | | | |
| | 7 | Upgrowth localised | | no | no | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | | | | | | |
| | 2 | Arable headland/field edge | | no | no | | | | | | |
| | 3 | Natural/set-aside but not above | | no | no | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | mud | Mud/grv | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | na | na | | | | | | |
| | 2 | Headland (field edge) ploughed | | no | no | | | | | | |
| | 3 | Path surface damaged/broken up | | no | no | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | | | | | | |
| | 5 | Upgrowth (on pathway) | | minor | none | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | no | none | | | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | no | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | | | | | | |
| | 4 | Intimidating beast/person | | no | no | | | | | | |
| | 5 | Collapsed wall | | no | no | | | | | | |
| | 6 | Encroachment (not by ploughing) | | no | no | | | | | | |
| | 7 | Quarrying or extraction | | no | no | | | | | | |
| | 8 | Plantation for forestry | | no | no | | | | | | |

| | | | |
|-----|---------------------------------|--|---|
| key | Summary of work required | | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | Fingerpost at start is new, crush gate (chicane) is VERY narrow (under 50cm). No CBC wm at leg2 or leg3. Waymarks and information sign erected by farmer (LEAF). | |
| M | Missing | | |
| A | Attention | FP16 is not DDA compliant due to crush gate width. | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|------------------|--------|----------------------|--------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP19 04/04/18 wet Barton Hill Track |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0928 2951 | 0893 2926 | 0892 2927 | | | | | |
|----------------------------|--------------------------------|-------------------------------------|----|--------------|--------------|--------------|---|---|---|---|---|
| | 1: PATH FURNITURE | | | leg 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | none | none | none | | | | | |
| | 2 | Waymark/other sign along path | | good | none | faded | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | no | | | | | |
| | 4 | Steps/revetment | | no | no | no | | | | | |
| | 5 | Bridges (length in meters) | | no | no | no | | | | | |
| | 6 | Styles | | no | no | no | | | | | |
| | 7 | Gates | | 1x CG | no | no | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | no | | | | | | |
| | 2 | Tree/brough | | no | no | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | no | | | | | | |
| | 4 | Illegal or misleading sign | | no | no | | | | | | |
| | 5 | Building or structure | | no | no | | | | | | |
| | 6 | Muddy/boggy localised | | no | no | | | | | | |
| | 7 | Upgrowth localised | | no | no | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | no | | | | | | |
| | 2 | Arable headland/field edge | | NNR | NNR | | | | | | |
| | 3 | Natural/set-aside but not above | | no | no | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | grass | Mud/grv | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | na | na | | | | | | |
| | 2 | Headland (field edge) ploughed | | no | no | | | | | | |
| | 3 | Path surface damaged/broken up | | no | no | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | no | no | | | | | | |
| | 5 | Upgrowth (on pathway) | | minor | minor | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | no | minor | | | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | no | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | no | | | | | | |
| | 4 | Intimidating beast/person | | no | no | | | | | | |
| | 5 | Collapsed wall | | no | no | | | | | | |
| | 6 | Encroachment (not by ploughing) | | no | no | | | | | | |
| | 7 | Quarrying or extraction | | no | no | | | | | | |
| | 8 | Plantation for forestry | | no | no | | | | | | |

| | | | |
|-----|----------------|--|--|
| key | | Summary of work required Waymarker at Leg1 is good KG at leg1 is std and not RADAR. No waymarker at Leg2, Waymarker at leg3 is faded. NO SIGNED CONNECTION TO BLC FP1 and BLC BW16 information sign erected by NE at Leg1 and Leg3. Surface is grass and well maintained however some overgrowth on leg3. | Added to ViewRanger data base yes - no |
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |
| | | FP19 is not DDA compliant due to non RADAR Kissing Gates width. | BARTON CONTRYSIDE CONSERVATION |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|-------------------------|--------|-----------------------------|---------------------|--|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP23 16/03/18 wet Hexton Way |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | | TL | 0900 3114 | 0877 3114 | | | | | | |
|----------------------------|--------------------------------|-------------------------------------|----|--------------|--------------|---|---|---|---|---|---|
| | 1: PATH FURNITURE | | | leg 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| G M A R | 1 | Signpost/Fingerpost (roadside) | | M fp>bw | M fp>bw | | | | | | |
| | 2 | Waymark/other sign along path | | good | Good | | | | | | |
| | 3 | Safety/amenity barrier eg.cycle | | no | no | | | | | | |
| | 4 | Steps/revetment | | no | no | | | | | | |
| | 5 | Bridges (length in meters) | | no | no | | | | | | |
| | 6 | Styles | | no | no | | | | | | |
| | 7 | Gates | | no | no | | | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | | no | | | | | | | |
| | 2 | Tree/brough | | no | | | | | | | |
| | 3 | Temporary deposit (eg straw bales) | | no | | | | | | | |
| | 4 | Illegal or misleading sign | | no | | | | | | | |
| | 5 | Building or structure | | no | | | | | | | |
| | 6 | Muddy/boggy localised | | muddy | | | | | | | |
| | 7 | Upgrowth localised | | medium | | | | | | | |
| | 3: SURFACE TYPE | | | | | | | | | | |
| M A R K | 1 | Cross arable land | | no | | | | | | | |
| | 2 | Arable headland/field edge | | headland | | | | | | | |
| | 3 | Natural/set-aside but not above | | no | | | | | | | |
| | 4 | Surfaced (tarmac, stone etc) | | grass | | | | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | | na | | | | | | | |
| | 2 | Headland (field edge) ploughed | | na | | | | | | | |
| | 3 | Path surface damaged/broken up | | no | | | | | | | |
| | 4 | Flooded/rutted/boggy/muddy | | wet | | | | | | | |
| | 5 | Upgrowth (on pathway) | | minor | | | | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | | minor | | | | | | | |
| | 2 | Standing water (pool/pond/lake) | | no | | | | | | | |
| | 3 | Barbed wire/electric fence adjacent | | no | | | | | | | |
| | 4 | Intimidating beast/person | | no | | | | | | | |
| | 5 | Collapsed wall | | no | | | | | | | |
| | 6 | Encroachment (not by ploughing) | | no | | | | | | | |
| | 7 | Quarrying or extraction | | no | | | | | | | |
| | 8 | Plantation for forestry | | no | | | | | | | |

| | | | |
|-----|----------------|--|---|
| key | | Summary of work required Both ends have no finger posts but do have waymarker posts (only signed as footpath), eastern post is heavily overgrown and hard to see from distance. Track passable but slippery after rain. FP23 is DDA compliant. | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | | |
| M | Missing | | |
| A | Attention | | |
| R | Repair/replace | | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**

PUBLIC RIGHTS OF WAY SURVEY FORM (BCC/SF1)

| | | | | |
|------------------|--------|----------------------|--------------|---|
| Local Authority: | CBC | Footpath / Bridleway | ROW Number: | FP33 16/03/18 wet Old Mill Lane |
| Parish: | BARTON | Unrestricted Byway | Sub section: | |
| Surveyor: | JSLT | Restricted Byway | Survey Date: | |

| | GRID REFERENCE & MAP POINT | TL | 0777 3132 | 0787 3121 | 0789 3121 | 0790 3121 | 0796 3121 | | | |
|----------------------------|--------------------------------|-------------------------------------|--------------|--------------|--------------|--------------|--------------|--|--|--|
| | 1: PATH FURNITURE | | | | | | | | | |
| G M A R | 1 | Signpost/Fingerpost (roadside) | attention | Good | none | none | none | | | |
| | 2 | Waymark/other sign along path | good | none | none | no | none | | | |
| | 3 | Safety/amenity barrier eg.cycle | x2 post | no | no | no | | | | |
| | 4 | Steps/revetment | no | no | no | no | | | | |
| | 5 | Bridges (length in meters) | no | no | no | no | | | | |
| | 6 | Styles | no | no | no | no | | | | |
| | 7 | Gates | no | no | no | no | | | | |
| | 2: OBSTRUCTIONS | | | | | | | | | |
| T I C K | 1 | Wall/fence (inc electric) hedge etc | no | no | no | no | | | | |
| | 2 | Tree/brough | no | no | no | no | | | | |
| | 3 | Temporary deposit (eg straw bales) | no | no | no | no | | | | |
| | 4 | Illegal or misleading sign | no | no | no | no | | | | |
| | 5 | Building or structure | no | no | no | no | | | | |
| | 6 | Muddy/boggy localised | no | no | no | no | | | | |
| | 7 | Upgrowth localised | none | none | medium | medium | | | | |
| | 3: SURFACE TYPE | | | | | | | | | |
| M A R K | 1 | Cross arable land | no | no | no | no | | | | |
| | 2 | Arable headland/field edge | no | driveway | highway | pavement | | | | |
| | 3 | Natural/set-aside but not above | no | no | no | no | | | | |
| | 4 | Surfaced (tarmac, stone etc) | grass | tarmac | tarmac | tarmac | | | | |
| | 4: OBSTRUCTIONS SURFACE | | | | | | | | | |
| A S R E | 1 | Cross field not reinstated | na | na | na | na | | | | |
| | 2 | Headland (field edge) ploughed | na | na | na | na | | | | |
| | 3 | Path surface damaged/broken up | no | no | no | no | | | | |
| | 4 | Flooded/rutted/boggy/muddy | no | no | no | no | | | | |
| | 5 | Upgrowth (on pathway) | mown | none | none | none | | | | |
| | 5: OBSTRUCTIONS | | | | | | | | | |
| Q U I R E D | 1 | Overgrowth (eg hedge beside path) | no | no | minor | minor | | | | |
| | 2 | Standing water (pool/pond/lake) | no | no | no | no | | | | |
| | 3 | Barbed wire/electric fence adjacent | no | no | no | no | | | | |
| | 4 | Intimidating beast/person | no | no | no | no | | | | |
| | 5 | Collapsed wall | no | no | no | no | | | | |
| | 6 | Encroachment (not by ploughing) | no | no | no | no | | | | |
| | 7 | Quarrying or extraction | no | no | no | no | | | | |
| | 8 | Plantation for forestry | no | no | no | no | | | | |

| | | | |
|-----|---------------------------------|---|---|
| key | Summary of work required | | Added to ViewRanger data base yes - no BARTON CONTRYSIDE CONSERVATION |
| G | Good | FP not marked from eastern end. | |
| M | Missing | Finger post at LEG1 pointing the wrong way, Chiltern Society finger marker vandalised. | |
| A | Attention | Some section marked as ped/cycle route? | |
| R | Repair/replace | FP33 is DDA compliant. | |

SURVEYORS SIGNATURE

Additional Survey information:

Route Photo recorded **yes** Route GPS logged no Map attached and ammended **yes**